Helderle

Copy 98

TOP SECRET



JOINT EVALUATION OF SOVIET MISSILE THREAT IN CUBA

PREPARED BY

Guided Missile and Astronautics Intelligence Committee

Joint Atomic Energy Intelligence Committee

National Photographic Interpretation Center

0200 HOURS

2 NOVEMBER 1962

Archival Record

Return to Archives & Records Center

TOP SECRET mediately After Use

GROUP | Excluding from automatic downgrading and declars ification 25X

Approved For Release	2007/09	9/04 : CIA	-RDP78T054	49A00020016	0001-4
		SECRE			

25X1

SUPPLEMENT 12

TO

JOINT EVALUATION OF SOVIET MISSILE THREAT IN CUBA

PREPARED BY

Guided Missile and Astronautics Intelligence Committee
Joint Atomic Energy Intelligence Committee
National Photographic Interpretation Center

0200 HOURS

2 NOVEMBER 1962

TOP SECRET

Approved For Release 2007/09/04 : CIA-RDP78T05449A000200160001-4	25
	25
	25
+	
NOTICE	1
This report is based primarily on preliminary analysis of low-level photography made on	25
SUMMARY	
1. We conclude that the Soviets are abandoning the known MRBM and IRBM sites in Cuba. (See Figures 4, 5 and 6.)	
2. All of the known MRBM sites are now being or have been dismantled. The missiles, basic launching equipment, and camouflage have been removed. The launch sites have been partially destroyed, apparently by bulldozing.	
3. The present location of the removed equipment and missiles is	
unknown. Because we have not had high altitude survey coverage since	25
we cannot exclude the existence of alternate redeployment sites.	25
4. Construction activity at the IRBM sites has stopped and the instal-	
ations at Guanajay partially destroyed.	
,	25

- 6. None of the Soviet cargo ships now in Cuba are capable of carrying IRBMs or MRBMs internally. The seven suspect missile carriers could return to Cuba between 16 and 25 November. Loading of missiles could take as much as a week.
- 7. There has been further progress in the assembly of IL-28 bomber aircraft at San Julian airfield since the last photographic coverage on
- 8. Potential command and control communication links have been identified for the Soviet rocket forces in Cuba. High frequency radio links between Moscow and Havana, which went over to scrambler operations on 28 October 1962, and microwave links to the former launch sites were probably intended to provide this control.
- 9. It is now possible to trace the development of the Soviet air defense system in Cuba indicating that an integrated, fully operational capability was achieved on 27 October.

Approved For Release 2007/09/04 : CIA-RDP78T05449A000200160001-4 TOP SECRET	25X1
	25X1
DISCUSSION	Ŋ
OFFENSIVE MISSILE READINESS	
San Cristobal MRBM Area	
1. Site 1 (22-40-05N 83-17-50W)	
Last coverage: Low-level	25X1 25X1
a. Readiness Status	
This site is no longer operational.	
b. Supporting Evidence	
All four launch positions are empty. The configuration of these positions has been altered; they are either covered or broken up. One launch stand is apparently being crated next to the position. Six missile-ready tents are still up. There are nine oxidizer trailers parked outside of the security fence and one parked inside. Four fuel trailers have not changed position since the last coverage. The AAA position at this site is unoccupied.	
c. Significant Trends	
The movement of missiles and direct support equipment since indicates that this site is no longer operational.	25X′
2. Site 2 (22-41-00N 83-15-00W)	257
Last coverage: Low-level	25X ²
a. Readiness Status	-
This site no longer has an operational capability.	

- 3 -

25X1

b. Supporting Evidence

The missile transporters, erectors and launch stands have been moved and are no longer visible at the site. The following missile support equipment has also been moved: fuel trailers, electronic vans, theodolite stations, generators and cables. It appears that camouflage has been removed. Three oxidizer trailers are parked in the same position as when previously seen and a few general purpose vehicles are observed in the area. Of the five missile-ready tents erected at this site, the positions of two of them were observed on this mission. One of these two had been removed while the other was still present. The two AAA positions at this site are occupied.

c. Significant Trends

The movement of missiles and support equipment from this MRBM site since the date of last coverage indicates that it no longer has an operational capability.

25X1

3. Site 3 (22-42-40N 83-08-25W)

Last coverage: Low-level

25X1 25X1

a. Readiness Status

This site probably does not have an operational capability.

b. Supporting Evidence

Only one launch position was observed on this mission and it appears to be completely abandoned.

c. Significant Trends

The movement of missiles and missile support equipment from one position of this site indicates that, in all probability, the entire site no longer has an operational capability.

- 4 -

TOP SECRET

Approved For Release 2007/09/04 : CIA-RDP78T05449A000200160001-4	25X1 25X1
	25X1
4. Site 4 (22-46-55N 82-58-50W) (See Figure 4.) Last coverage: Low-level	25X1
	25X1

a. Readiness Status

This site no longer has an operational capability.

b. Supporting Evidence

The missile transporters, erectors and launch stands at the two positions observed have been moved and are no longer visible. The following missile support equipment has also been removed: propellant trailers, theodolite stations, electronic vans, generators and cables. It appears that all camouflage has been removed. One missile-ready tent is gone and three others are either masked by trees or have been removed. There are a large number of miscellaneous vehicles scattered around the area and eight trucks loaded with wood forms are leaving the area in convoy. The tent area is essentially unchanged. The AAA position at this site is occupied.

c. Significant Trends

The movement of missiles and support equipment from the visible positions of this site indicates that in all probability this MRBM site no longer has an operational capability.

Sagua La Grande MRBM Area

5.	Site 1 (22-43-44N 80-01-40W) (See Figure 5.)	
	Last coverage: Low-level	25X1
		25 X 1

a. Readiness Status

This site no longer has an operational capability.

b. Supporting Evidence

TOP SECRET

- 5 -

25X1

25X1

The erectors, launch stands and cabling are no longer in the area. The launch pad configuration has been obliterated. There is no change in the tent area and the support area remains unchanged. Two missile-ready tents are still up and many vehicles are parked in the open in the support area. There are four cranes in the support area. There is no evidence of camouflage; thirteen oxidizer trailers and eight fuel trailers are parked in the open. There is no change in the nuclear weapons storage bunker which has been under construction since ______ There is new fencing at the south end of the site and also new fencing across the road between the support area and launch area.

c. Significant Trends

The movement of missiles and direct support equipment indicates that this site is no longer operational.

6. Site 2 (22-39-10N 79-51-55W)

Last coverage: Low-level

25X1

a. Readiness Status

This site no longer has an operational capability.

b. Supporting Evidence

The erector and launch stand on the one position seen at this site have been moved and are no longer visible. However, one missile-ready tent remains and fourteen oxidizer and seven fuel trailers are parked in the open. Camouflage has been removed and the cabling at the position is no longer visible. A large number of miscellaneous vehicles are scattered throughout the area.

c. Significant Trends

The movement of the erector, launch stand and cabling from the position seen indicates that this site is being evacuated and in all prob-

- 6 -

Approved For Release 2007/09/04 : CIA-RDP78T05449A000200160001-4 TOP SECRET
ability no longer has an operational capability.
Guanajay IRBM Area
7. Site 1 (22-57-00N 82-39-25W) (See Figure 6.)
Last coverage: Low-level
a. Readiness Status
This IRBM site was being evacuated, and has no operational
capability.
b. Supporting Evidence
The foundations for the launch stands and some of the pre-cast concrete conduit appears to have been torn up and the equipment removed. There are trucks, prime movers, trailers, and powered heavy construction equipment visible in a support area about one mile south of the site. Other heavy construction equipment is assembled in an open storage area. Tents, which had been erected near the site, were gone at the time of this mission.
c. Significant Trends
This IRBM site, under active construction through at least is being deactivated with the removal of missile ground support equipment. Some destruction of concrete work was in evidence.
8. Site 2 (22-57-25N 82-36-55W)
Last coverage: Low-level
a. Readiness Status
This IRBM site has no operational capability as it is incomplete

This IRBM site has no operational capability as it is incomplete and construction activity has ceased.

- 7 -

	Approved For Release 2007/09/04 : CIA-RDP78T05449A000200 TOP SECRET	0160001-4
	b. Supporting Evidence	
	There has been no apparent construction progre	ss on this IRBM
site sir		Between this site
and Site	e 1 approximately sixty trucks are assembled, aligne	d in three rows.
	c. Significant Trends	
tion equ	Construction has been stopped on this IRBM site a uipment and vehicles have been assembled in one ar	
Remedi	ios IRBM Area	
9.	Site 1 (22-25-00N 79-35-00W)	
	Last coverage: Low-level	
	a. Readiness Status	
,	This IRBM site has no operational capability.	
	b. Supporting Evidence	
	No construction progress has been made on this s	
	ly stage of construction Construction Construction	truction activity
PPCGID	c. Significant Trends	
	No vehicles, personnel, or other signs of activity	ty are visible at
	e.	ty are visible at

Approved For Release 2007/09/04 : CIA-RDP78T05449A000200160001-4



25X1 25X1

COMMAND AND CONTROL

- 11. No specific link has been definitely identified as the Command Link between Moscow and the sites deployed in Cuba, however, there are ample communications facilities which could be utilized. Those links between the USSR and Cuba which could serve are:
 - a. ILC (Morse)
 - b. ILCS (Radiotelephone)
 - c. KGB direct (Morse)
 - d. KGB relayed thru Conakry (Morse)
 - e. KGB relayed thru Bamako (Morse)
 - f. VLF Broadcast (KUDMA) from Moscow (Morse)
 - g. HF Broadcast (Suspect Rocket Forces) from Moscow (Morse)
 - h. "Link A" Moscow to Havana (Morse and Scrambler)
 - i. "Link B" USSR to Cuba (Morse and Scrambler)
- 12. Of the above, "a" through "e" are not considered suitable for command purposes because of relatively slow transmission speed and low data handling capability. The two broadcasts, "f" and "g", are one-way only and would require another link to pass traffic back to Moscow.
- 13. The two links, "h" and "i", are considered the most likely ones for command communications. These links first appeared on passing Morse traffic. They began scrambler operations on by which date all MRBM sites were believed to have become operational. Scrambler provides the volume, speed and security believed necessary for missile command and control.
- 14. Within Cuba, microwave towers have been located in low-level photography at the following MRBM and IRBM sites:
 - a. San Cristobal Site 1
 - b. San Cristobal Site 3
 - c. Guanajay Site 1

- 10 -

TOP SECRET

25X1

- Sagua La Grande Site 2 d.
- Remedios e.
- 15. The orientation of these antennas suggests that they link the launch sites with a location in the Havana area. None of these antennas is a part of the Cuban National VHF/UHF Network.
- 16. The existence of an alternate means of communications between the Havana area and these sites is suggested by the large number of $\ensuremath{\mathsf{MF}}/\ensuremath{\mathsf{HF}}$ communications vans observed at the sites.
- 17. It appears that direct radio links from Moscow to Havana provide communications between Headquarters, Strategic Rocket Forces in Moscow and the Division Headquarters in Havana. The microwave circuits between Havana and the sites probably link Division Headquarters with each of the Regimental Headquarters.

SUPPLY AND LOGISTICS

- 18. The time necessary for final implementation of an order to remove Soviet offensive missile systems will be governed by the availability of Soviet ships suitable for return transport of the ballistic missile units. We believe three weeks would be the minimum time required for the proper Soviet ships to reach Cuba and load missile cargoes. It is more likely that at least four weeks would be required to accomplish this.
- 19. Seven Soviet ships capable of carrying MRBMs/IRBMs have been identified among the ships carrying military equipment to Cuba. We do not know the number of missiles carried on each trip by any given ship and cannot be certain when any ship did or did not carry missiles. However, we believe that no less than five and possibly as many as eight voyages by these Soviet ships were necessary to deliver the MRBMs observed.
- 20. None of the suspect missile carriers are now near Cuba, nor are any of the Soviet cargo ships now in Cuba capable of carrying IRBMs or

TOP SECRET

25X1

- 11 -

Approved For Release 2007/09/04 : CIA-RDP78T05449A000200160001-4 TOP SECRET
MRBMs internally. Several of suspect carriers only recently arrived back in Soviet ports and the rest probably will be in by the end of the week. All even possible missile carriers could be en route back to Cuba in ballast by the beginning of next weekaround 4/5 November. Several could have tarted by now, but thus far we have no evidence that any of them are under ay. Once under way, the trip back to Cuba would take about two weeks, utting them in Cuban ports between 16 and 25 November. Loading of misiles and missile equipment could take another week.
COASTAL DEFENSE
No change
IR DEFENSE MISSILES
21. The surface-to-air missile sites (SA-2) at San Julian and Santa ucia were photographed from low-level on The RUITSET radar and missiles on launchers were canvas covered at San ulian. At the Santa Lucia site, the FRUITSET radar was uncovered but the missiles were canvas covered and turned parallel to the drive-through pad. Both sites showed evidence of heavy rain. The cables from the midance radar to the launchers are raised on supports above ground.

22. The development of the Soviet air defense system in Cuba is traced in the following paragraphs:

a. Early May -

25X1

Beginning as early as May 1962, the Cuba Revolutionary Air Force (CRAF) was expanded and, with the introduction of Mig 15, Mig 17, Mig 19, and later Mig 21 aircraft had a greatly increased capability. Fighters were

- 12 -

TOP SECRET


Approved For Release 2007/09/0 TOP S	04 : CIA-RDP78T05449A000200160001-4 SECRET
lrag chute landing, aerial gunner apparent through the use of Russ. The Soviets at this time were apparent These aircraft were deployed the Los Banos, Santa Clara, and Carle Communications with CRAF he The mission of the CRAF, prosupport with contributory air deferment of the the first lawere noted. The bearings were converged to the contributory are defermented.	at the CRAF headquarters at San Antonio amaguey. The latter two field maintained eadquarters. rior to September, was primarily ground
D.	



Approved For Release 2007/09/04 : CIA-RDP78T05449A000200160001-4 TOP SECRET	
TACTICAL MISSILES	
No change	
BOMBERS	
23. Photography of San Julian Airfield on had revealed 21 crated IL-28's and six partially assembled IL-28's, of which two were	
the 21 crated fuselages, with wing and empennage crates, had	d e
peen dispersed to individual hardstands. Of the seven partially assembled combers, two are apparently operational, and one was taxing at the time of coverage. One of the incomplete aircraft is the trainer version (MAS-	
peen dispersed to individual hardstands. Of the seven partially assembled combers, two are apparently operational, and one was taxing at the time	;



Approved For Release 2007/09/04 : CIA-RDP78T05449A000200160001-4



Approved For Release 2007/09/04 : CIA-RDP78T05449A000200160001-4

TOP 25X1:CRET






FIGURE 4. SAN CRISTOBAL MRBM SITE 4,




FIGURE 5. SAGUA LA GRANDE MRBM SITE 1,

25X1 25X1 25X1



25X1 25X1



TOP	SECRET